


The event will begin momentarily.

- This event is being recorded
- Captions are available by clicking the CC icon in the Zoom toolbar below
- ASL is provided
- Presentation materials are available at: www.access-board.gov

Designing for Inclusion: Architectural Trends and Social Justice



Presenters



Karen L. Braitmayer Studio Pacifica-Seattle FAIA, Principal



Deborah A. Ryan Deborah A. Ryan & Associates

Agenda

Architecture and Social Justice


Architectural Trends

Pandemic-Related Trends

Questions

Social Stairs















All Gender Toilet Room – Model Codes

2021 IBC Chapter 29 – 2902.2 Separate Facilities

Exception 5. Separate facilities shall not be required to be designated by sex where single-user toilet rooms are provide in accordance with Section 2902.1.2.

Exception 6. Separate facilities shall not be required where rooms having both water closets and lavatory fixtures are designed for use by both sexes and privacy for water closets are installed in accordance with Section 405.3.4 of the Intl. Plumbing Code. Urinals shall be located in an area visually separated from the remainder of the facility or each urinal that is provided shall be located in a stall.

All Gender Toilet Room – WA Codes

WA State Building Code 2021 - 2902.2.2 Gender-neutral facilities. Gender-neutral toilet facilities, when provided, shall be in accordance with the following:

1. There is no reduction in the number of fixtures required to be provided for male and female in the type of occupancy and in the minimum number shown in Table 2902.1.

2. Gender-neutral multiuser toilet rooms shall have water closets and urinals located in toilet compartments in accordance with ICC A117.1.


3. Gender-neutral multiuser toilet room water closet and urinal compartments shall have full-height walls and a door enclosing the fixture to ensure privacy.

4. Gender-neutral toilet room water closet and urinal compartment doors shall be securable from within the compartment.

5. Gender-neutral toilet rooms provided for the use of multiple occupants, the egress door from the room shall not be lockable from the inside of the room.

6. Compartments shall not be required in a single-occupant toilet room with a lockable door.


All Gender Toilet Room Plan






University of Washington North Campus Housing Graham Baba Architects in collaboration with Kieran Timberlake






Urinals





Toilet Room Trends







Lavatory Trends





Adult Changing Tables







Bottle Fillers



Point-of-Sale Machines




- Must comply as operable parts where fixed
- Communication access is important (but not addressed by the standards)


Smart Environments/Self-Service Transaction Machines





Tactile Wayfinding






Scooter/Bicycle Litter








Pandemic Trends




Dining Trends: Bar & High-Top Seating







Dining Surfaces








Accessible Dining Tables




Route to Outdoor Dining Surfaces







Outdoor Elevated Decks







Inaccessible Restaurants


- Many restaurants in this historic neighborhood are inaccessible due to narrow sidewalks and steps at the entrance with no possibility of ramping.
- Opportunity missed to make at least the outdoor dining accessible.
- Raise the area level with the sidewalk and provide accessible tables




Outdoor Dining - Missed Opportunities









Missed Opportunities (continued)









Accessible Route but No Accessible Seating






Outdoor Dining - High-Top Tables – Again





Accessible Outdoor Dining

 Although not perfect, the seating area is raised and level with the sidewalk AND the tables are accessible!





Final Thoughts:

- If seating is provided in the street down from the sidewalk, provide raised decking level with the sidewalk for easy access
- Provide accessible seating within the outdoor dining area.

• Provide an accessible route to the accessible seating

Doors





Service Trends





Social Distancing




Directional Signage





Touchless






Partitions



Hand Hygiene Stations







Ask yourself: "Who does this design exclude?"



Questions



Technical Assistance

•(800) 872-2253 (voice)

•(800) 993-2822 (TTY)

- E-mail: ta@access-board.gov
- •www.access-board.gov





Thank you for joining us today.

